Table 1. Summary of	Resu	lt:
---------------------	------	-----

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS RE-SAMPLING RESULTS						CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS		
CATEGORY	SAMPLE ID	Outlet Description	Comments	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	nmeded Level = 20ppb Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE				8/3/2019			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE				8/12/2019			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
DRINKING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A

E-1 Enclosure (1)

Outlet Description	Comments			Lead Screen	ing Level of 20ppb				Recom	meded Level = 20nnh
Outlet Description	Commonts								Recommeded Level = 20ppb	
	Comments	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
		8/3/2019			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
		8/12/2019			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
		non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
			non-detect	non-detect NO	non-detect NO N/A	non-detect NO N/A N/A	non-detect NO N/A N/A N/A	non-detect NO N/A N/A N/A N/A	non-detect NO N/A N/A N/A N/A Routine Control Measures Only	non-detect NO N/A N/A N/A N/A Routine Control Measures Only N/A

E-2 Enclosure (1)

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS RE-SAMPLING RESULTS						CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS			
						Lead Screen	ing Level of 20ppb				Recommeded Level = 20ppb		
CATEGORY	SAMPLE ID	Outlet Description	Comments	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	
SAMPLING DATE				0/2/2010					mm/dd/yyyy				
RESULTS DATE				8/3/2019 8/12/2019			mm/dd/yyyy mm/dd/yyyy		mm/dd/yyyy			mm/dd/yyyy mm/dd/yyyy	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A	

E-3 Enclosure (1)

	SAMPLING LOCATION DESCRIPTION					RESULTS		MPLING RESU	LTS	CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS	
						Lead Screer	ning Level of 20ppb				Recommeded Level = 20ppb	
CATEGORY	SAMPLE ID	Outlet Description	Comments	First Draw (ppb)	Retest required?	Date Fixture Secured? (See Note 1)	Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)
SAMPLING DATE				8/3/2019			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
RESULTS DATE				8/12/2019			mm/dd/yyyy	mm/dd/yyy	mm/dd/yyyy			mm/dd/yyyy
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A
WASHING				non-detect	NO	N/A	N/A	N/A	N/A	Routine Control Measures Only	N/A	N/A

Notes:

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS	RE-SAMPLING RESULTS POST REMEDIATION RESULTS										
	Lead Screening Level of 20ppb											
	First Draw (ppb)		Water Fountain Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	First Draw (ppb)						
Total Drinking	17		0	0	0	0						
Total Drinking > 20 ppb	0		0	0	0	0						
Total Cook	3		0	0	0	0						
Total Cook> 20 ppb	0		0	0	0	0						
Total Washing	52		0	0	0	0						
Total Washing > 20 ppb	0		0	0	0	0						
Total Samples	72		0	0	0	0						
Total Samples > 20 ppb	0		0	0	0	0						

E-4 Enclosure (1)

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on 09/10/2019 are shown on the table.